## Surveyor: Zaw La Date Visited: 25.5.2016 Time Visited: 10:15 to 11:15

<u>Weather Condition: Sunny</u> <u>The last time of heavy raining: - yesterday</u>

No	Item	Condition	Description and Photos					
1	Condition of	of -						
	(1). Well	Improved□ Same <b>©</b> * Worse □ *as last week	Description & Photos: -See ANNEX.1 - Water from both of two wells is clean and can be used for drinking and living. But the amount of water in both wells is being decreased during these days. There are four tube wells in the relocation site. Among them, one of the hand pump needs to be repaired, but people can get water from their own tube-wells, the two open-wells and the rest of two hand pumps.					
	(2).	Improved□	Description					
	Drainage	Same <b>©</b> * Worse □ *as last week	There is a little amount of water in the drainage canals. The stream along the drainage canal may need to be rehabilitated in coming summer period in order to improve the water-flow along the stream. Photos					
			<image/>					
			<image/>					


(3). Road	Improved	In front of HH No. 1
	■*     Same □     Worse □     *as last     week	-The roads are being dry and no problem for walking. <u>Photos</u>
		Front main road
		Middle road       The left road of relocation site         Image: Stress of the left road of relocation site       Image: Stress of the left road of relocation site         Image: Stress of the left road of relocation site       Image: Stress of the left road of relocation site         Image: Stress of the left road of relocation site       Image: Stress of the left road of relocation site         Image: Stress of the left road of relocation site       Image: Stress of the left road of relocation site         Image: Stress of the left road of relocation site       Image: Stress of the left road of relocation site         Image: Stress of the left road of relocation site       Image: Stress of the left road of relocation site         Image: Stress of the left road of relocation site       Image: Stress of the left road of relocation site         Image: Stress of the left road of relocation site       Image: Stress of the left road of relocation site         Image: Stress of the left road of relocation site       Image: Stress of the left road of relocation site         Image: Stress of the left road of relocation site       Image: Stress of the left road of relocation site         Image: Stress of the left road of relocation site       Image: Stress of the left road of relocation site         Image: Stress of the left road of the left road of relocation site       Image: Stress of the left road
(4). Garbage Condition	Improved□ Same <b>©*</b> Worse □	Description- People do not want to use garbage pit again They do not like people to take washing clothes and showering near the well and therefore garbage pit was demolished and water storage tank has been constructed instead of itTrash from all houses will be collected by garbage truck biweekly until starting of the community fundThere is a small vegetable planting field at the backside of Third Row where there were many trashes before the vegetable plantation was started.

			<image/>
			Back side of third role
<u>N</u> 0 1	Item (5). Fly proof toilet	Condition Improved ■* Same □ *as last week	Description         -All of the fly proof toilets are used by people.         -Almost all of the fly proof toilets made by wood or bamboo have been lifted up as shown in pictures below and are convenient to use. Some concrete toilets are still needed to be renovated. According to discussion with community people, they would like to repair the concrete toilets by themselves and requested for financial support.         JET had already paid for it.         Condition       No. of HHs         Very 1       SO         Condition       No. of of HHs         Very 2       17         Level 1       SO         SO       O         Level 2       17         Level 3       O         No Toilet       1         Very 1       -Fly proof toilet is not needed to be repaired.         -No/rarely toilet unavailable       Level 3         Level 3       -Fly proof toilet is needed to be repaired.         -Rarely toilet unavailable       -Fly proof toilet is needed to be repaired.         -Fly proof toilet is needed to be repaired.       -Ghen toilet unavailable         Level 3       -Fly proof toilet is needed to be repaired.         -Fly proof toilet is needed to be repaired.       -Ghen toilet unavailable         Level 4       -Fly proof toilet is needed to be repaired.         -Often toilet unavailable       -As the

		-Often toilet unavailable					
		Level 1       HH No. 6         Image: HH No. 6       HH No. 12         Image: HH No. 12       HH No. 12					
		Level 3       HH No. 31         Image: Hubble 2       Hubble 2         Image: Hubble 2					
(6). Electricity	Improved ■* Same □ Worse □ *as last week	<u>Description</u> -Electricity comes regularly. -Electric poles and transformer are being supported with a good foundation. -There was a hole at an electric pole which was hit by a truck car but the electric pole was renovated. <u>Photos</u>					
		<image/>					


No 2	ltem House		ndition . of	Description and Description	a Photos				
	Construct houses not -ion completed (2)		uses not mpleted	-HH No.5, the construction for kitchen, toilet and water tank seems to be stopped again.					
			HH No. 5						
3	Living Status of		<u>scription</u> House ow	cription House ownership					
	PAPs (Sold			(1)-1 No. of house that are owned by PAPs (45)					
	house,	(2)	(1)-2 No. of house that were sold (23) Living condition						
	renting,		(2)-1 No. of houses where PAPs live (37)						
	etc.)			<ul><li>(2)-2 No. of houses where original PAPs do not live (28)</li><li>(2)-3 No. of houses where nobody lives (3)</li></ul>					
				cation Map: See ANNEX.2					
4	Other issue								
	(1). Drainag condition fo		<u>Descriptic</u>	ווכ					
	rain water i			No. of HH	ts				
	their		Conditio						
	compounds	5	Level 1	condition 63	n condition 63				
			Level 2	5	5				
			Level 3	0	0				
			Level 4	0	0				
	<evaluation criteria=""></evaluation>								
			Level 1						
				and no standing v	water with their own drainage system in their compound				
			<i>Level 2</i> -No mud	and no standing v	water in their compound				
	-No mud and no standing water in their compound Level 3								
	- Some or little mud and standing water in their compound								
	Level 4								

		-A lot of mud and standing water in their compound					
		<u>Photos</u>					
		HH No. 47		Level 1 HH No. 45	vel 3		
		HH No. 61		Level 4         Image: https://www.image.org/amag	evel 2		
4	(2) Plantation	Description -In front of their compounds, the people planted shady trees, fruit trees, vegetables and floral plants.					
		Туре	No. of HHs	Remarks	]		
		Shady tree	21	Albizzia, Indian almond, etc. HH No. 2, 3, 14, 15,16, 17, 18, 19, 20, 23, 25, 26, 27, 32, 33, 39, 41, 44, 48, 58 and 65			
		Fruit tree	27	Banana, Mango, sugarcane, coconut, citrus, etc. HH No.1, 2, 3, 4, 8, 9, 11, 17, 24, 25, 27, 29, 30, 34, 36, 37, 38, 39, 40, 41, 43, 45, 46, 47, 48, 65 and 67			
		Vegetable	11	Spices, peas, roselle, etc. HH No. 15, 23, 25, 38, 39, 40, 42,45, 58, 63 and 67			
		Floral plant	26	Many species. HH No. 2, 9, 14, 15, 17, 18, 19, 21, 26, 27, 30, 31, 32, 33, 38, 39, 40, 41, 42, 43, 47, 48, 58, 59, 62 and 65			



## ANNEX.1

## As of 25.5.2016



ANNEX.2

