Surveyor: Sithu Nyein
Date Visited: 18.8.2014
Time Visited: 10:00 to 12:30

Weather Condition: Sunny and partly cloudy
The last time of heavy raining: 15.8.2014

No	Item	Condition	Description and Photos	
1	Condition of -			
	(1). Well	Improved □ Same   *Worse □  *as good as	Description & Photos: See ANNEX.1	
		last week		
	(2). Drainage	Improved	<u>Description</u>	
		Same □	Water in the drainage canal is becoming lower than last week.	
		Worse □	Photos  A second of the second	
	(3). Road	Improved □ Same  * Same  * Worse □ *as good as last week	Description All roads are in good condition There are some puddles and partly muddy areas but the roads are almost dried and no problem for traffic as a whole.  Photos	
		ійѕт шеек		

No	Item	Condition	Description	n and Photos
1	(4). Garbage Pit	Improved □ Same □ Worse ■	Description Garbage pit is surrounded by water People are not using garbage pit	Photo Photo
	(5). Septic Tank	Improved <b>⑤</b> Same □ Worse □	Description -Some of the septic tanks are nearly full by waterMost of septic tanks are in good condition for use.  Condition No. of HHs Very Good 42 Good 21 Bad 0 Very Bad 0 No Toilet 5 <evaluation criteria=""> Very Good -No need to repair septic tank -No/rarely toilet available Good -Need to repair septic tank -Rarely toilet unavailable Bad -Need to repair septic tank -Often toilet unavailable Very Bad -Need to repair urgently septic tank -Often toilet unavailable</evaluation>	Photos  HH No. 7  Very Good  HH No. 65  Good
	(6). Electricity	Improved □ Same  * Worse □ *as good as last week	<u>Description</u> -Electricity is coming regularly	are in good foundation by concrete else.

No	Item	Condition	Description and Photos	
2	House Construction	No. of houses not completed (2)	Description -HH No.1 doesn't have ladder and nobody is living -In HH No.5, the construction for kitchen, toilet and water tank seems stopped. Nobody is livingIn HH No.5, sun shade of this house is collapsed due to wind. Wind is not so strong but the quality of the sun shade is not so good enough.  Photos  HH No. 1  HH No. 5  HH No. 5	
3	Living Status of PAPs (Sold house, renting, etc.)	(1)-2 N (2) No. of hous (2)-1 N (2)-2 N (3) No. of hous		

No	Item	Description and Photos		
4	Other issues	·		
	(1). Flood	<u>Description</u>		
	condition	-It is not severer condition during this week because it is less heavy raining.		
		-But there are some puddles and muddy areas in most of the compounds.		
		, ,		
		Condition No. of HHs		
		Very Good 6		
		Good 17		
		Bad 28		
		Very Bad 17		
		<evaluation criteria=""></evaluation>		
		Very Good		
		-No mud and no standing water with their own drainage system in their compound		
		Good		
		-No mud and no standing water in their compound		
		Bad - Some or little mud and standing water in their compound		
		Very Bad		
		-A lot of mud and standing water in their compound		
		·		
		HH No. 47  HH No. 65  Very Good  Good		
		HH No. 2  HH No. 7  Very Bad		

No	Item	Description and Photos	
4	(2) Garbage	Description -People threw the garbage in the backside of their compound over the fence especially who live in third rowSome people put the garbage near electrical transformer so this area become dirtier than last week -Garbage are also gathering in the drainage canal  Photos	
		Garbage at the backside of HH No.49  The backside of third row	
		Near transformer  Drainage canal near HH No.48	

## 5 Remarks

Ko Htay Naing (HH No.11) and Ko Zaw Myo Htet (HHNo.21) have been arrested by police because of being shot with stones to HH No.37 after they drunk. Today morining(18.8.2014) these two men are released as U Myint Thu and other community heads made an insurance for them. For now, both parties reconciled not to go for a cause.

ANNEX.1 Updated 18.8.2014



