
Surveyor:ZawLaDateVisited:2.5.2016TimeVisited:16:15 to 17:00

Weather Condition: Sunny The last time of heavy raining: -

No	Item	Condition	Description and Photos				
1	Condition o	of -					
	(1). Well	Improved□ Same©* Worse □ *as last week	Description & Photos: -See ANNEX.1 - Water from both of two wells is clean and can be used for drinking and living. But the amount of water in both wells is being decreased during these days. There are four tube wells in the relocation site. Among them, one of the hand pumps needs to be repaired, but people can get water from their own tube-wells, the two open-wells and the rest of two hand pumps.				
	(2). Drainage	Improved□ Same © * Worse □ *as last week	<u>Description</u> There is almost no water in the drainage canals. The stream along the drainage canal may need to be rehabilitated in coming summer period in order to improve the water-flow along the stream. <u>Photos</u>				
			<image/>				
			Near HH No. 1 Near garbage pit Near garbage pit Near garbage pit				


		In front of HH No. 1
(3). Road	Improved ■* Same □ Worse □ *as last	<u>Description</u> -The roads are being dry and no problem for walking. <u>Photos</u>
	week	Front main road The right road of relocation site Image: state Image: state Image: state Image: state<
		<image/>
(4). Garbage Condition	Improved□ Same © * Worse □	Description - People do not want to use garbage pit again. - They do not like people to take washing clothes and showering near the well and therefore garbage pit was demolished and water storage tank has been constructed instead of it. -Trash from all houses will be collected by garbage truck biweekly until starting of the community fund. -There is a small vegetable planting field at the backside of Third Row where there were many trashes before the vegetable plantation was started.

			<image/> <image/>				
<u>N</u> 0	<u>ltem</u> (5). Fly	Condition Improved	Description -All of the fly proof toilets are used by people.				
1	proof toilet	Same Worse *as last week	-Almost all of the fly proof toilets made by wood or bamboo have been lifted up as shown in pictures below and are convenient to use. Some concrete toilets are still needed to be renovated. According to discussion with community people, they would like to repair the concrete toilets by themselves and requested for financial support. JET had already paid for it. <u>No. of HHs</u> <u>Condition</u> This Previous <u>week</u> week <u>condition</u> condition <u>Level 1</u> 50 50 <u>Level 2</u> 17 17 <u>Level 3</u> 0 0 <u>Level 4</u> 0 0 <u>No Toilet</u> 1 1				
			<evaluation criteria=""></evaluation> <i>Level 1</i> Fly proof toilet is not needed to be repairedNo/rarely toilet unavailable <i>Level 2</i> Fly proof toilet is needed to be repairedRarely toilet unavailable <i>Level 3</i> Fly proof toilet is needed to be repairedOften toilet unavailable -As the result of filling the soil and also due to the heavy rain, some toilets are inconvenience to use. <i>Level 4</i> - Fly proof toilet is urgently needed to be repaired.				




No	ltem	Condition	Description and I	Photos			
2	House						
	Construct	houses not	-HH No.5, the construction for kitchen, toilet and water tank seems to be stopped				
	-ion	completed	again.				
		(2)	HH No. 5				
3	-	Living <u>Description</u>					
	Status of	(1) House ov	•	$r_{\rm are owned by DADs}(4\Gamma)$			
	PAPs (Sold		No. of house that	are owned by PAPs (45)			
	(Sold house,	(1)-2 (2) Living coi		were sold (23)			
	renting,		No. of houses whe	ere PAPs live (37)			
	etc.)			ere original PAPs do not live (28)			
				ere nobody lives (3)			
			p: See ANNEX.2				
4	Other issue						
	(1). Drainag		<u>on</u>				
	condition fo						
	rain water i		No. of HHs				
	their	Conditio					
	compounds		condition	condition			
		Level 1	63	63			
		Level 2	5	5			
		Level 3	0	0			
		Level 4	0	0			
	<evaluation criteria=""> Level 1</evaluation>						
			and no standing w	vater with their own drainage system in their compound			
		Level 2					
			and no standing w	vater in their compound			
		Level 3	Ū.				
	 Some or little mud and standing water in their compound Level 4 A lot of mud and standing water in their compound 						

		<u>Photos</u>				
		HH No. 47		Level 1 HH No. 45 Level 1 Level 1 Leve	vel 3	
		HH No. 61		Level 4 Image: Him No. 14 <	vel 2	
4	(2) Plantation	Description -In front of the	ir compounds,	ds, the people planted shady trees, fruit trees, vegetables and f		
		plants.			l	
		Type Shady trop	No. of HHs 21	Remarks		
		Shady tree	21	Albizzia, Indian almond, etc. HH No. 2, 3, 14, 15,16, 17, 18, 19, 20, 23, 25, 26, 27, 32, 33, 39, 41, 44, 48, 58 and 65		
		Fruit tree	27	Banana, Mango, sugarcane, coconut, citrus, etc. HH No.1, 2, 3, 4, 8, 9, 11, 17, 24, 25, 27, 29, 30, 34, 36, 37, 38, 39, 40, 41, 43, 45, 46, 47, 48, 65 and 67		
		Vegetable	11	Spices, peas, roselle, etc. HH No. 15, 23, 25, 38, 39, 40, 42,45, 58, 63 and 67		
		Floral plant	26	Many species. HH No. 2, 9, 14, 15, 17, 18, 19, 21, 26, 27, 30, 31,		
				32, 33, 38, 39, 40, 41, 42, 43, 47, 48, 58, 59, 62 and 65		



ANNEX.1

As of 2.5.2016



ANNEX.2

