
## Surveyor:ZawLaDate Visited:20.5.2016Time Visited:10:15 to 11:15

Weather Condition: Sunny The last time of heavy raining: -


No	ltem	Condition	Description and Photos			
1	Condition o	of -				
	(1). Well	Improved□ Same©* Worse □ *as last week	Description & Photos: -See ANNEX.1 - Water from both of two wells is clean and can be used for drinking and living. But the amount of water in both wells is being decreased during these days. There are four tube wells in the relocation site. Among them, one of the hand pumps needs to be repaired, but people can get water from their own tube-wells, the two open-wells and the rest of two hand pumps.			
	(2). Drainage	Improved□ Same <b>©</b> * Worse □ *as last week	<u>Description</u> There is almost no water in the drainage canals. The stream along the drainage canal may need to be rehabilitated in coming summer period in order to improve the water-flow along the stream. <u>Photos</u>			
			<image/>			
			Near HH No. 1         Near garbage pit			

		In front of HH No. 1		
(3). Road	Improved ■* Same □ Worse □ *as last	<u>Description</u> -The roads are being dry and no problem for walking. <u>Photos</u>		
	week	Front main road       The right road of relocation site         Image: State of the state of th		
		Middle roadImage: Construction of the state of th		
(4). Garbage Condition	Improved□ Same <b>©</b> * Worse □	Description- People do not want to use garbage pit again They do not like people to take washing clothes and showering near the well and therefore garbage pit was demolished and water storage tank has been constructed instead of itTrash from all houses will be collected by garbage truck biweekly until starting of the community fundThere is a small vegetable planting field at the backside of Third Row where there were many trashes before the vegetable plantation was started.		

			Garber pit       Washing clothes and taking bath place         Washing clothes and taking bath place       Image: Clothes and taking bath place         Back side of third role       Image: Clothes and taking bath place         Image: Clothes and taking bath place       Image: Clothes and taking bath place         Image: Clothes and taking bath place       Image: Clothes and taking bath place         Image: Clothes and taking bath place       Image: Clothes and taking bath place         Image: Clothes and taking bath place       Image: Clothes and taking bath place         Image: Clothes and taking bath place       Image: Clothes and taking bath place         Image: Clothes and taking bath place       Image: Clothes and taking bath place         Image: Clothes and taking bath place       Image: Clothes and taking bath place         Image: Clothes and taking bath place       Image: Clothes and taking bath place         Image: Clothes and taking bath place       Image: Clothes and taking bath place         Image: Clothes and taking bath place       Image: Clothes and taking bath place         Image: Clothes and taking bath place       Image: Clothes and taking bath place         Image: Clothes and taking bath place       Image: Clothes and taking bath place         Image: Clothes and taking bath place       Image: Clothes and taking bath place         Image: Clothes and taking bath place       Image: Clothes ath place			
<u>N</u> 0 1	Item (5). Fly proof toilet	Condition Improved ■* Same □ *as last week	Description         -All of the fly proof toilets are used by people.         -Almost all of the fly proof toilets made by wood or bamboo have been lifted up as shown in pictures below and are convenient to use. Some concrete toilets are still needed to be renovated. According to discussion with community people, they would like to repair the concrete toilets by themselves and requested for financial support. JET had already paid for it.         Image: The concrete toilets by themselves and requested for financial support. JET had already paid for it.         Image: The concrete toilets by themselves and requested for financial support. JET had already paid for it.         Image: The concrete toilets by themselves and requested for financial support. JET had already paid for it.         Image: The concrete toilets by themselves and requested for financial support. JET had already paid for it.         Image: The concrete toilets by themselves and requested for financial support. JET had already paid for it.         Image: The concrete toilets by themselves and requested for financial support. JET had already paid for it.         Image: The concrete toilets by themselves and requested for financial support. JET had already paid for it.         Image: The concrete to ilets by themselves and requested for financial support. JET had already paid for it.         Evel 1       50         Som Toilet 1       1         Image: Proof toilet is not needed to be repaired.         -No/rarely toilet unavailable         Level 3       - Fly proof toilet is needed to be repaired. </th			




No	Item	Condition	Description and Photos				
2	House	No. of					
	Construct	houses not	-HH No.5, the	-HH No.5, the construction for kitchen, toilet and water tank seems to be stopped			
-ion completed again.			again.				
		(2)					
			HH No. 5				
			- Alerta				
3	Living	Description					
	Status of	(1) House ov	wnership				
	PAPs		•	hat are owned by PAPs (45)			
	(Sold			hat were sold (23)			
	house,	(2) Living co	ndition				
	renting,	(2)-1	No. of houses v	where PAPs live (37)			
	etc.)			where original PAPs do not live (28)			
(2)-3 No. of houses where nobody lives (3)							
<u> </u>	0.1		cation Map: See ANNEX.2				
4	Other issue						
	(1). Drainag		lon				
	rain water i		No. of H	Hc			
	their	Conditi					
	compounds		conditio				
	een peanae	Level 1	63	63			
		Level 2	5	5			
		Level 3	0	0			
		Level 4	0	0			
	<evaluation criteria=""> Level 1</evaluation>						
	-No mud and no standing water with their own drainage system in their compound						
		Level 2					
	<ul> <li>-No mud and no standing water in their compound</li> <li><i>Level 3</i></li> <li>- Some or little mud and standing water in their compound</li> <li><i>Level 4</i></li> </ul>						
-A lot of mud and standing water in their compound				ing water in their compound			



4	(3) Livestock	<b>Description</b>			
		-The people ar		en,	
		ducks, goats, p -Even though t		s some	
		PAPs do not ke			
		relocation site			
		their farms or		·	
			1	1	-
		Туре	No. of HHs	Remarks	-
		Cow	4	HH No. 1, 42, 47	
		Pig	1	and 54 HH No. 48	
		Goat	3	HH No.15, 47, 50	
		Chicken and	18	HH No. 3, 4, 8, 12,	-
		ducks	_	14, 15, 20, 28, 30,	
				32, 41, 47, 50, 51,	
				52, 54, 56 and 62	
I		<u>Photos</u>			

## ANNEX.1

## As of 20.5.2016



ANNEX.2

