

Weekly Field Report

No. 15


Surveyor: Sithu Nyein


Date Visited: 02.12.2014








Time Visited: 10:30 to 12:00



Weather Condition: Sunny


The last time of heavy raining: -

| No | Item | Condition | Description and Photos |
|----|----------------|---|---|
| 1 | Condition of - | | |
| | (1). Well | Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i> | Description & Photos: -See ANNEX.1 -Hand Pump of Well No. 6, 9 and 11 are needed to repair. |
| | (2). Drainage | Improved <input checked="" type="checkbox"/> Same <input type="checkbox"/> Worse <input type="checkbox"/> | Description -Water level in the drainage canal is near to the bottom. Photos  |
| | (3). Road | Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i> | Description -The roads are almost dry and no problem for traffic as a whole. |

| | | | |
|------------------------|--|---|---|
| | | | <p><u>Photos</u></p>  |
| (4). Garbage Condition | | <p>Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/>* Worse <input type="checkbox"/> <i>*as last week</i></p> | <p><u>Description</u></p> <ul style="list-style-type: none"> -Garbage pit is used by people. -Garbage pit is almost half-full. -There is no strong smell.  |

| No | Item | Condition | Description and Photos | | | | | | | | | | | | | | | | | | | | | |
|-----------|-----------------------|---|---|---|------------|--|---------------------|-------------------------|---------|----|----|---------|----|----|---------|---|---|---------|---|---|-----------|---|---|--|
| 1 | (5). Fly proof toilet | Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i> | <u>Description</u> -All of fly proof toilets are being used by people. | <u>Photos</u>    | | | | | | | | | | | | | | | | | | | | |
| | | | <table border="1"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>42</td> <td>42</td> </tr> <tr> <td>Level 2</td> <td>21</td> <td>21</td> </tr> <tr> <td>Level 3</td> <td>0</td> <td>0</td> </tr> <tr> <td>Level 4</td> <td>0</td> <td>0</td> </tr> <tr> <td>No Toilet</td> <td>5</td> <td>5</td> </tr> </tbody> </table> <u><Evaluation Criteria></u> Level 1 -No need to repair fly proof toilet -No/rarely toilet unavailable Level 2 -Need to repair fly proof toilet -Rarely toilet unavailable Level 3 -Need to repair fly proof toilet -Often toilet unavailable Level 4 -Need to repair urgently fly proof toilet -Often toilet unavailable | Condition | No. of HHs | | This week condition | Previous week condition | Level 1 | 42 | 42 | Level 2 | 21 | 21 | Level 3 | 0 | 0 | Level 4 | 0 | 0 | No Toilet | 5 | 5 | |
| Condition | No. of HHs | | | | | | | | | | | | | | | | | | | | | | | |
| | This week condition | Previous week condition | | | | | | | | | | | | | | | | | | | | | | |
| Level 1 | 42 | 42 | | | | | | | | | | | | | | | | | | | | | | |
| Level 2 | 21 | 21 | | | | | | | | | | | | | | | | | | | | | | |
| Level 3 | 0 | 0 | | | | | | | | | | | | | | | | | | | | | | |
| Level 4 | 0 | 0 | | | | | | | | | | | | | | | | | | | | | | |
| No Toilet | 5 | 5 | | | | | | | | | | | | | | | | | | | | | | |
| | (6). Electricity | Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i> | <u>Description</u> -Electricity is coming regularly -Electric poles and transformer are supported in good foundation. | <u>Photos</u>     | | | | | | | | | | | | | | | | | | | | |

| No | Item | Condition | Description and Photos | | | | | | | | | | | | | | | | | |
|-----------|---|--|---|-----------|------------|--|---------------------|-------------------------|---------|----|----|---------|----|----|---------|----|----|---------|---|---|
| 2 | House Construction | No. of houses not completed (2) | <p><u>Description</u></p> <p>-HH No.1 doesn't have ladder and nobody is living -In HH No.5, the construction for kitchen, toilet and water tank seems stopped. Nobody lives.</p> <p><u>Photos</u></p> <div style="display: flex; justify-content: space-around;">   </div> | | | | | | | | | | | | | | | | | |
| 3 | Living Status of PAPs (Sold house, renting, etc.) | <p><u>Description</u></p> <p>(1) House ownership (1)-1 No. of house that are owned by PAPs (49) (1)-2 No. of house that were sold (19)</p> <p>(2) Living condition (2)-1 No. of houses where PAPs live (39) (2)-2 No. of houses where not original PAPs lives (24) (2)-3 No. of houses where nobody lives (5)</p> | <p>Location Map: See ANNEX.2</p> | | | | | | | | | | | | | | | | | |
| 4 | Other issues | | <p>(1). Drainage condition for rain water in their compounds</p> <p><u>Description</u></p> <p>-Rainy season is over. -Most of the compounds are almost dry.</p> <table border="1" style="margin-left: 20px;"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>15</td> <td>15</td> </tr> <tr> <td>Level 2</td> <td>43</td> <td>38</td> </tr> <tr> <td>Level 3</td> <td>10</td> <td>15</td> </tr> <tr> <td>Level 4</td> <td>0</td> <td>0</td> </tr> </tbody> </table> <p><Evaluation Criteria></p> <p>Level 1 -No mud and no standing water with their own drainage system in their compound</p> <p>Level 2 -No mud and no standing water in their compound</p> <p>Level 3 - Some or little mud and standing water in their compound</p> <p>Level 4 -A lot of mud and standing water in their compound</p> | Condition | No. of HHs | | This week condition | Previous week condition | Level 1 | 15 | 15 | Level 2 | 43 | 38 | Level 3 | 10 | 15 | Level 4 | 0 | 0 |
| Condition | No. of HHs | | | | | | | | | | | | | | | | | | | |
| | This week condition | Previous week condition | | | | | | | | | | | | | | | | | | |
| Level 1 | 15 | 15 | | | | | | | | | | | | | | | | | | |
| Level 2 | 43 | 38 | | | | | | | | | | | | | | | | | | |
| Level 3 | 10 | 15 | | | | | | | | | | | | | | | | | | |
| Level 4 | 0 | 0 | | | | | | | | | | | | | | | | | | |





4 (2)
Plantation

Description
-In front of their compounds, they planted shady trees, fruit trees, vegetables and floral plants.

| Type | No. of HHs | Remarks |
|--------------|------------|--|
| Shady tree | 12 | Albizia, Indian almond, etc. HH No. 2, 3, 14, 19, 20, 21, 25, 27, 29, 32, 41 and 65 |
| Fruit tree | 24 | Banana, Mango, sugarcane, coconut, citrus, etc. HH No. 2, 3, 4, 7, 8, 9, 11, 17, 21,24, 25, 27, 33, 37, 38, 39, 41, 43, 45, 46, 47, 48, 54 and 65 |
| Vegetable | 10 | Spices, peas, roselle, etc. HH No. 22, 23, 25, 27, 38, 39, 40, 42,45 and 63 |
| Floral plant | 20 | Many species. HH No. 2, 9, 14, 15, 17,21, 23, 27, 32, 33, 38, 39, 40, 41, 42, 43, 47, 48, 58 and 65 |





| 4 | (3) Livestock | <p><u>Description</u> -They are raising chicken, ducks, goats, pigs and cows. -Even though they have cows, they do not keep their cows in relocation site instead they keep in their farms or other places.</p> <table border="1" data-bbox="400 730 1026 1061"> <thead> <tr> <th>Type</th> <th>No. of HHs</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>Cow</td> <td>5</td> <td>HH No. 3, 18, 42, 47 and 54</td> </tr> <tr> <td>Pig</td> <td>-</td> <td>-</td> </tr> <tr> <td>Goat</td> <td>2</td> <td>HH No. 50 and 51</td> </tr> <tr> <td>Chicken and ducks</td> <td>15</td> <td>HH No. 4, 8, 12, 14, 28, 30, 32, 41, 47, 50, 51, 52, 55, 56 and 62</td> </tr> </tbody> </table> <p><u>dPhotos</u></p> <div style="display: flex; justify-content: space-around;">   </div> | Type | No. of HHs | Remarks | Cow | 5 | HH No. 3, 18, 42, 47 and 54 | Pig | - | - | Goat | 2 | HH No. 50 and 51 | Chicken and ducks | 15 | HH No. 4, 8, 12, 14, 28, 30, 32, 41, 47, 50, 51, 52, 55, 56 and 62 |
|-------------------|----------------|---|------|------------|---------|-----|---|-----------------------------|-----|---|---|------|---|------------------|-------------------|----|--|
| Type | No. of HHs | Remarks | | | | | | | | | | | | | | | |
| Cow | 5 | HH No. 3, 18, 42, 47 and 54 | | | | | | | | | | | | | | | |
| Pig | - | - | | | | | | | | | | | | | | | |
| Goat | 2 | HH No. 50 and 51 | | | | | | | | | | | | | | | |
| Chicken and ducks | 15 | HH No. 4, 8, 12, 14, 28, 30, 32, 41, 47, 50, 51, 52, 55, 56 and 62 | | | | | | | | | | | | | | | |
| 5 | Remarks | -In HH No.2, pigs are sold out. There are no more pigs. | | | | | | | | | | | | | | | |



Water is clean and has no sand, no clay and no smell. People are using this well for cooking and washing. Sometimes they are drinking



The color of water likes gray and has no sand, no clay and no smell. People are not using this well. Because nearby well No. 2 and 10 are used.



Hand pump is functioned. Water is clean and has no sand, no clay but it has smell of mud. People are using this well for washing. Some people who live nearby buy water from private well of HH No.43 for washing, cooking and drinking. They have to pay 100 Ks per day of use. They take water to their houses with movable pipe.

Hand pump isn't functioned very well. The washer needs to be repaired. People are using this well for cooking and washing. Sometimes they are drinking.

Hand pump isn't functioned.

Hand pump isn't functioned very well. The washer needs to be repaired. The color of water likes red. People who live nearby aren't using this well. People buy water from private well of HH No.4 for washing, cooking and drinking. They have to pay 100 Ks per day of use. They take water to their houses with movable pipe.



- Closed Well**
- New Well (Hand pump)**
- Open Well**
- Hand Pump**
- Private Well**

Hand pump is functioned. Water is clean and has no sand, no clay, and no smell. People are using this well for cooking and washing. Sometimes they are drinking.





-  Main Road
-  Sub-road
-  Proposed Road
-  Existing Road
-  Drainage
-  Creek
-  HHs that are owned by PAPs (49)
-  HHs that were sold (19)
-  HHs where original PAPs are living (39)
-  HHs that are rented by other people (24)
-  HHs where nobody is living (5)
-  HHs that were built by constructor (12)