

## Weekly Field Report

No. 20


Surveyor: Sithu Nyein



Date Visited: 8.1.2015








Time Visited: 13:00 to 14:30


Weather Condition: Sunny

The last time of heavy raining: -

No	Item	Condition	Description and Photos
1	Condition of - (1). Well	Improved <input type="checkbox"/> Same <input type="checkbox"/> Worse <input checked="" type="checkbox"/>	Description & Photos: -See ANNEX.1. -Hand Pump of Well No. 6, 8, 9, 10 and 11 need to be repaired. (All of the hand pumps need to be repaired. They use some of these hand pumps but it is not too comfortable.)
	(2). Drainage	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<p><u>Description</u> -Water level in the drainage canal is near to the bottom.</p> <p><u>Photos</u></p> 
	(3). Road	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<p><u>Description</u> -The roads are almost dry and no problem for traffic as a whole.</p>

			<p><u>Photos</u></p> 
(4). Garbage Condition	<p>Improved <input type="checkbox"/></p> <p>Same <input type="checkbox"/></p> <p>Worse <input checked="" type="checkbox"/></p>	<p><u>Description</u></p> <ul style="list-style-type: none"> <li>-Garbage pit is used by people.</li> <li>-Garbage pit is over full.</li> <li>-There are some smells from garbage pit.</li> <li>-People throw garbage at the backside of Third Row.</li> </ul>	

No	Item	Condition	Description and Photos																					
1	(5). Fly proof toilet	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<u>Description</u> -All of fly proof toilets are used by people.	<u>Photos</u>   																				
			<table border="1"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>42</td> <td>42</td> </tr> <tr> <td>Level 2</td> <td>21</td> <td>21</td> </tr> <tr> <td>Level 3</td> <td>0</td> <td>0</td> </tr> <tr> <td>Level 4</td> <td>0</td> <td>0</td> </tr> <tr> <td>No Toilet</td> <td>5</td> <td>5</td> </tr> </tbody> </table> <u>&lt;Evaluation Criteria&gt;</u> <b>Level 1</b> -No need to repair fly proof toilet -No/rarely toilet unavailable <b>Level 2</b> -Need to repair fly proof toilet -Rarely toilet unavailable <b>Level 3</b> -Need to repair fly proof toilet -Often toilet unavailable <b>Level 4</b> -Need to repair urgently fly proof toilet -Often toilet unavailable	Condition	No. of HHs		This week condition	Previous week condition	Level 1	42	42	Level 2	21	21	Level 3	0	0	Level 4	0	0	No Toilet	5	5	
Condition	No. of HHs																							
	This week condition	Previous week condition																						
Level 1	42	42																						
Level 2	21	21																						
Level 3	0	0																						
Level 4	0	0																						
No Toilet	5	5																						
	(6). Electricity	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<u>Description</u> -Electricity comes regularly. -Electric poles and transformer are supported in good foundation.	<u>Photos</u>    																				

No	Item	Condition	Description and Photos																	
2	House Construction	No. of houses not completed (2)	<p><u>Description</u>            -HH No.1 doesn't have ladder and nobody lives.            -In HH No.5, the construction for kitchen, toilet and water tank seems stopped. Nobody lives.</p> <p><u>Photos</u></p> 																	
3	Living Status of PAPs (Sold house, renting, etc.)	<p><u>Description</u>            (1) House ownership                (1)-1 No. of house that are owned by PAPs (49)                (1)-2 No. of house that were sold (19)            (2) Living condition                (2)-1 No. of houses where PAPs live (39)                (2)-2 No. of houses where not original PAPs lives (21)                (2)-3 No. of houses where nobody lives (8)</p>	<p>Location Map: See ANNEX.2</p>																	
4	Other issues		<p>(1). Drainage condition for rain water in their compounds</p> <p><u>Description</u>            -Rainy season is over.            -Most of the compounds are almost dry.</p> <table border="1" data-bbox="400 1323 989 1563"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>14</td> <td>14</td> </tr> <tr> <td>Level 2</td> <td>54</td> <td>54</td> </tr> <tr> <td>Level 3</td> <td>0</td> <td>0</td> </tr> <tr> <td>Level 4</td> <td>0</td> <td>0</td> </tr> </tbody> </table> <p><b>&lt;Evaluation Criteria&gt;</b>  <b>Level 1</b>            -No mud and no standing water with their own drainage system in their compound  <b>Level 2</b>            -No mud and no standing water in their compound  <b>Level 3</b>            - Some or little mud and standing water in their compound  <b>Level 4</b>            -A lot of mud and standing water in their compound</p>	Condition	No. of HHs		This week condition	Previous week condition	Level 1	14	14	Level 2	54	54	Level 3	0	0	Level 4	0	0
Condition	No. of HHs																			
	This week condition	Previous week condition																		
Level 1	14	14																		
Level 2	54	54																		
Level 3	0	0																		
Level 4	0	0																		



4 (2)  
Plantation

Description



-In front of their compounds, they planted shady trees, fruit trees, vegetables and floral plants.


Type	No. of HHs	Remarks
Shady tree	12	Albizzia, Indian almond, etc. HH No. 2, 3, 14, 19, 20, 21, 25, 27, 29, 32, 41 and 65
Fruit tree	24	Banana, Mango, sugarcane, coconut, citrus, etc. HH No. 2, 3, 4, 7, 8, 9, 11, 17, 21,24, 25, 27, 33, 37, 38, 39, 41, 43, 45, 46, 47, 48, 54 and 65
Vegetable	10	Spices, peas, roselle, etc. HH No. 22, 23, 25, 27, 38, 39, 40, 42,45 and 63
Floral plant	20	Many species. HH No. 2, 9, 14, 15, 17,21, 23, 27, 32, 33, 38, 39, 40, 41, 42, 43, 47, 48, 58 and 65

Photos





4	(3) Livestock	<p><u>Description</u></p> <p>-They are raising chicken, ducks, goats, pigs and cows.          -Even though they have cows, they do not keep their cows in relocation site instead they keep in their farms or other places.</p> <table border="1" data-bbox="399 728 1029 1064"> <thead> <tr> <th>Type</th> <th>No. of HHs</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>Cow</td> <td>5</td> <td>HH No. 3, 18, 42, 47 and 54</td> </tr> <tr> <td>Pig</td> <td>-</td> <td>-</td> </tr> <tr> <td>Goat</td> <td>1</td> <td>HH.47</td> </tr> <tr> <td>Chicken and ducks</td> <td>15</td> <td>HH No. 4, 8, 12, 14, 28, 30, 32, 41, 47, 50, 51, 52, 55, 56 and 62</td> </tr> </tbody> </table>	Type	No. of HHs	Remarks	Cow	5	HH No. 3, 18, 42, 47 and 54	Pig	-	-	Goat	1	HH.47	Chicken and ducks	15	HH No. 4, 8, 12, 14, 28, 30, 32, 41, 47, 50, 51, 52, 55, 56 and 62
Type	No. of HHs	Remarks															
Cow	5	HH No. 3, 18, 42, 47 and 54															
Pig	-	-															
Goat	1	HH.47															
Chicken and ducks	15	HH No. 4, 8, 12, 14, 28, 30, 32, 41, 47, 50, 51, 52, 55, 56 and 62															
		<p><u>Photos</u></p> <div style="display: flex; justify-content: space-around;">   </div>															
5	<p><b>Remarks</b></p> <ul style="list-style-type: none"> <li>- HH No.26 has a private well now. They finished digging the well on 7 January, 2015. The type of well is tube well ( 200ft depth). According to this household head said, it costed around 6 lakhs kyats ( 600,000 MMK) in total.</li> </ul>																



Water is clean and has no sand, no clay and no smell. People use this well for cooking and washing. Sometimes they drink.



Hand pump isn't functioned very well. The washer needs to be repaired. People use this well for washing. Some people who live nearby buy water from private well of HH No.43 for washing, cooking and drinking. They have to pay 100 Ks per day of use. They take water to their houses with movable pipe.



Hand pump isn't functioned very well. The washer needs to be repaired. People use this well for cooking and washing. Sometimes they drink.



Hand pump isn't functioned.

The color of water likes gray. People don't use this well. Because nearby well No. 2 and 10 are used.



Hand pump isn't functioned very well. The washer needs to be repaired. People don't use this well. People buy water from private well of HH No.4 for washing, cooking and drinking. They have to pay 100 Ks per day of use. They take water to their houses with movable pipe.



Water is clean and has no sand, no clay and no smell. People not only from relocation site but also from host community use this well especially for drinking.



Hand pump isn't functioned very well. The washer needs to be repaired. People use this well for cooking and washing. Sometimes they drink.

- Closed Well
- New Well (Hand pump)
- Open Well
- Hand Pump
- Private Well

