

Weekly Field Report

No. 17


Surveyor: Sithu Nyein



Date Visited: 17.12.2014








Time Visited: 10:00 to 11:30


Weather Condition: Sunny


The last time of heavy raining: -

No	Item	Condition	Description and Photos
1	Condition of -		
	(1). Well	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	Description & Photos: -See ANNEX.1. -Hand Pump of Well No. 6, 9, 10 and 11 are needed to repair.
	(2). Drainage	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<p><u>Description</u> -Water level in the drainage canal is near to the bottom.</p> <p><u>Photos</u></p> 
	(3). Road	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<p><u>Description</u> -The roads are almost dry and no problem for traffic as a whole.</p>

			<p><u>Photos</u></p> 
(4). Garbage Condition	<p>Improved <input type="checkbox"/></p> <p>Same</p> <p>Worse <input checked="" type="checkbox"/></p>	<p><u>Description</u></p> <ul style="list-style-type: none"> -Garbage pit is used by people. -Garbage pit is nearly full. -There is no strong smell. -People throw garbage at the backside of Third Row. 	

No	Item	Condition	Description and Photos																				
1	(5). Fly proof toilet	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<p><u>Description</u> -All of fly proof toilets are used by people.</p> <table border="1"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>42</td> <td>42</td> </tr> <tr> <td>Level 2</td> <td>21</td> <td>21</td> </tr> <tr> <td>Level 3</td> <td>0</td> <td>0</td> </tr> <tr> <td>Level 4</td> <td>0</td> <td>0</td> </tr> <tr> <td>No Toilet</td> <td>5</td> <td>5</td> </tr> </tbody> </table> <p><Evaluation Criteria> Level 1 -No need to repair fly proof toilet -No/rarely toilet unavailable Level 2 -Need to repair fly proof toilet -Rarely toilet unavailable Level 3 -Need to repair fly proof toilet -Often toilet unavailable Level 4 -Need to repair urgently fly proof toilet -Often toilet unavailable</p> <p><u>Photos</u></p>   	Condition	No. of HHs		This week condition	Previous week condition	Level 1	42	42	Level 2	21	21	Level 3	0	0	Level 4	0	0	No Toilet	5	5
Condition	No. of HHs																						
	This week condition	Previous week condition																					
Level 1	42	42																					
Level 2	21	21																					
Level 3	0	0																					
Level 4	0	0																					
No Toilet	5	5																					
	(6). Electricity	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<p><u>Description</u> -Electricity comes regularly. -Electric poles and transformer are supported in good foundation.</p> <p><u>Photos</u></p>    																				

No	Item	Condition	Description and Photos																	
2	House Construction	No. of houses not completed (2)	<p><u>Description</u></p> <p>-HH No.1 doesn't have ladder and nobody lives. -In HH No.5, the construction for kitchen, toilet and water tank seems stopped. Nobody lives.</p> <p><u>Photos</u></p> 																	
3	Living Status of PAPs (Sold house, renting, etc.)	<p><u>Description</u></p> <p>(1) House ownership (1)-1 No. of house that are owned by PAPs (49) (1)-2 No. of house that were sold (19)</p> <p>(2) Living condition (2)-1 No. of houses where PAPs live (39) (2)-2 No. of houses where not original PAPs lives (21) (2)-3 No. of houses where nobody lives (8)</p> <p>Yellow= Changes from previous week</p>	<p>Location Map: See ANNEX.2</p>																	
4	Other issues		<p>(1). Drainage condition for rain water in their compounds</p> <p><u>Description</u></p> <p>-Rainy season is over. -Most of the compounds are almost dry.</p> <table border="1" data-bbox="400 1357 987 1599"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>14</td> <td>15</td> </tr> <tr> <td>Level 2</td> <td>49</td> <td>42</td> </tr> <tr> <td>Level 3</td> <td>5</td> <td>11</td> </tr> <tr> <td>Level 4</td> <td>0</td> <td>0</td> </tr> </tbody> </table> <p><Evaluation Criteria></p> <p>Level 1 -No mud and no standing water with their own drainage system in their compound</p> <p>Level 2 -No mud and no standing water in their compound</p> <p>Level 3 - Some or little mud and standing water in their compound</p> <p>Level 4 -A lot of mud and standing water in their compound</p>	Condition	No. of HHs		This week condition	Previous week condition	Level 1	14	15	Level 2	49	42	Level 3	5	11	Level 4	0	0
Condition	No. of HHs																			
	This week condition	Previous week condition																		
Level 1	14	15																		
Level 2	49	42																		
Level 3	5	11																		
Level 4	0	0																		



4 (2)
Plantation

Description

-In front of their compounds, they planted shady trees, fruit trees, vegetables and floral plants.

Type	No. of HHs	Remarks
Shady tree	12	Albizzia, Indian almond, etc. HH No. 2, 3, 14, 19, 20, 21, 25, 27, 29, 32, 41 and 65
Fruit tree	24	Banana, Mango, sugarcane, coconut, citrus, etc. HH No. 2, 3, 4, 7, 8, 9, 11, 17, 21,24, 25, 27, 33, 37, 38, 39, 41, 43, 45, 46, 47, 48, 54 and 65
Vegetable	10	Spices, peas, roselle, etc. HH No. 22, 23, 25, 27, 38, 39, 40, 42,45 and 63
Floral plant	20	Many species. HH No. 2, 9, 14, 15, 17,21, 23, 27, 32, 33, 38, 39, 40, 41, 42, 43, 47, 48, 58 and 65

Photos





4 (3) Livestock

Description


-They are raising chicken, ducks, goats, pigs and cows.
 -Even though they have cows, they do not keep their cows in relocation site instead they keep in their farms or other places.

Type	No. of HHs	Remarks
Cow	5	HH No. 3, 18, 42, 47 and 54
Pig	-	-
Goat	2	HH No. 50 and 51
Chicken and ducks	15	HH No. 4, 8, 12, 14, 28, 30, 32, 41, 47, 50, 51, 52, 55, 56 and 62

dPhotos



5 Remarks





-  Main Road
-  Sub-road
-  Proposed Road
-  Existing Road
-  Drainage
-  Creek
-  HHs that are owned by PAPs (49)
-  HHs that were sold (19)
-  HHs where original PAPs are living (39)
-  HHs that are rented by other people (21)
-  HHs where nobody is living (8)
-  HHs that were built by constructor (12)