

Weekly Field Report

No. 26


Surveyor: Zaw La



Date Visited: 27.4.2015








Time Visited: 13:00 to 14:30

Weather Condition: Sunny



The last time of heavy raining: -

No	Item	Condition	Description and Photos
1	Condition of -		
	(1). Well	Improved <input checked="" type="checkbox"/> * Same <input type="checkbox"/> Worse <input type="checkbox"/> <i>*as last week</i>	Description & Photos: -See ANNEX.1. -Hand Pump of Well No. 6, and 10 is work well but 8 and 9 need to be dig more to get sufficient water continuously. Because the water will be yellowed color after getting 5 or 6 bucket.
	(2). Drainage	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<p><u>Description</u> -Water level in the drainage canal is near to the bottom.</p> <p><u>Photos</u></p>  <p>The above 4 pictures are shown before repairing situation. The rest of 2 pictures are shown current situation digging the canal not to be flooded.</p>

	(3). Road	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<u>Description</u> -The roads are almost dry and no problem for traffic as a whole.
			<u>Photos</u> 
	(4). Garbage Condition	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/>	<u>Description</u> -Garbage pit is used by people. -Garbage pit is over full. -There are some smells from garbage pit. -People throw garbage at the backside of Third Row. 

																								
No	Item	Condition	Description and Photos																					
1	(5). Fly proof toilet	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<u>Description</u> -All of fly proof toilets are used by people. <table border="1"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>42</td> <td>42</td> </tr> <tr> <td>Level 2</td> <td>21</td> <td>21</td> </tr> <tr> <td>Level 3</td> <td>0</td> <td>0</td> </tr> <tr> <td>Level 4</td> <td>0</td> <td>0</td> </tr> <tr> <td>No Toilet</td> <td>5</td> <td>5</td> </tr> </tbody> </table> <u><Evaluation Criteria></u> Level 1 -No need to repair fly proof toilet -No/rarely toilet unavailable Level 2 -Need to repair fly proof toilet -Rarely toilet unavailable Level 3 -Need to repair fly proof toilet -Often toilet unavailable Level 4 -Need to repair urgently fly proof toilet -Often toilet unavailable	Condition	No. of HHs		This week condition	Previous week condition	Level 1	42	42	Level 2	21	21	Level 3	0	0	Level 4	0	0	No Toilet	5	5	<u>Photos</u>   
Condition	No. of HHs																							
	This week condition	Previous week condition																						
Level 1	42	42																						
Level 2	21	21																						
Level 3	0	0																						
Level 4	0	0																						
No Toilet	5	5																						
	(6). Electricity	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<u>Description</u> -Electricity comes regularly. -Electric poles and transformer are supported in good foundation.	<u>Photos</u>  																				



No	Item	Condition	Description and Photos																	
2	House Construction	No. of houses not completed (2)	<p><u>Description</u></p> <p>-HH No.1 doesn't have ladder and nobody lives. -In HH No.5, the construction for kitchen, toilet and water tank seems stopped.</p> <p><u>Photos</u></p> <div style="display: flex; justify-content: space-around;"> <div style="text-align: center;">  <p>HH No. 1</p> </div> <div style="text-align: center;">  <p>HH No. 5</p> </div> </div>																	
3	Living Status of PAPs (Sold house, renting, etc.)	<p><u>Description</u></p> <p>(1) House ownership (1)-1 No. of house that are owned by PAPs (49) (1)-2 No. of house that were sold (19)</p> <p>(2) Living condition (2)-1 No. of houses where PAPs live (39) (2)-2 No. of houses where not original PAPs lives (22) (2)-3 No. of houses where nobody lives (7)</p>	<p>Location Map: See ANNEX.2</p>																	
4	Other issues		<p>(1). Drainage condition for rain water in their compounds</p> <p><u>Description</u></p> <p>-Rainy season is over. -Most of the compounds are almost dry.</p> <table border="1" style="margin-left: 20px;"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>14</td> <td>14</td> </tr> <tr> <td>Level 2</td> <td>54</td> <td>54</td> </tr> <tr> <td>Level 3</td> <td>0</td> <td>0</td> </tr> <tr> <td>Level 4</td> <td>0</td> <td>0</td> </tr> </tbody> </table>	Condition	No. of HHs		This week condition	Previous week condition	Level 1	14	14	Level 2	54	54	Level 3	0	0	Level 4	0	0
Condition	No. of HHs																			
	This week condition	Previous week condition																		
Level 1	14	14																		
Level 2	54	54																		
Level 3	0	0																		
Level 4	0	0																		

<Evaluation Criteria>
Level 1
 -No mud and no standing water with their own drainage system in their compound
Level 2
 -No mud and no standing water in their compound
Level 3
 - Some or little mud and standing water in their compound
Level 4
 -A lot of mud and standing water in their compound



4 (2)
Plantation

Description
 -In front of their compounds, they planted shady trees, fruit trees, vegetables and floral plants.

Type	No. of HHs	Remarks
Shady tree	12	Albizia, Indian almond, etc. HH No. 2, 3, 14, 19, 20, 21, 25, 27, 29, 32, 41 and 65
Fruit tree	24	Banana, Mango, sugarcane, coconut, citrus, etc. HH No. 2, 3, 4, 7, 8, 9, 11, 17, 21, 24, 25, 27, 33, 37, 38, 39, 41, 43, 45, 46, 47, 48, 54 and 65
Vegetable	10	Spices, peas, roselle, etc. HH No. 22, 23, 25, 27, 38, 39, 40, 42, 45 and 63
Floral plant	20	Many species. HH No. 2, 9, 14, 15, 17, 21, 23, 27, 32, 33, 38, 39, 40, 41, 42, 43, 47, 48, 58 and 65



4 (3) Livestock

Description
 -They are raising chicken, ducks, goats, pigs and cows.
 -Even though they have cows, they do not keep their cows in relocation site instead they keep in their farms or other places.

Type	No. of HHs	Remarks
Cow	5	HH No. 3, 18, 42, 47 and 54
Pig	-	-
Goat	1	HH.47
Chicken and ducks	15	HH No. 4, 8, 12, 14, 28, 30, 32, 41, 47, 50, 51, 52, 55, 56 and 62



5 **Remarks**

ANNEX.1

As of 25.3.2015

