

## Biweekly Field Report

No. 2 \_\_\_\_\_







Surveyor Zaw La





Weather Condition Sunny





Date visited 5 Jan 2018

The last time of heavy raining \_\_\_\_\_

Time visited 13:30 pm


No	Item	Condition	Description and Photos
1	(1) Well	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<p>– Water from two open-wells is clean and can be used for drinking and living. There are eleven tube wells in the relocation site. Among them, three of the tube wells need to be repaired, but people using water mainly from pipeline water supply system.</p>
			<div style="display: flex; flex-wrap: wrap; justify-content: space-around;"> <div style="text-align: center;">  <p>Open Well No. 1</p> </div> <div style="text-align: center;">  <p>Open Well No. 2</p> </div> <div style="text-align: center;">  <p>Tube Well No. 1</p> </div> <div style="text-align: center;">  <p>Tube Well No. 2</p> </div> <div style="text-align: center;">  <p>Tube Well No. 3</p> </div> <div style="text-align: center;">  <p>Tube Well No. 4</p> </div> </div>








			 <p>Tube Well No.5</p>  <p>Tube Well No.10</p>  <p>Tube Well No.7</p>  <p>Tube Well No.6</p>
--	--	--	--

(2) Drainage	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	– There is no water in the drainage canals at the moment. <u>Photos</u>	
		 <p>Drain at the corner of Main Road A and B</p>	 <p>Drain exit at the corner of Site village road and 2<sup>nd</sup> street</p>
		 <p>Drain exit at the corner of Site village road and 3<sup>rd</sup> street</p>	 <p>Drain exit at the corner of Site village road and Main Road C</p>

(3) Road	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/>	– All the roads are dry and no problem for walking. <u>Photos</u>
----------	---	--

*\*as last week*



			 <p>7<sup>th</sup> Street</p>	 <p>Site Village Road</p>
	<p>(4) Garbage Condition</p>	<p>Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/>* Worse <input type="checkbox"/> <i>*as last week</i></p>	<ul style="list-style-type: none"> <li>– People threw the trash at the corner of road, beside the creek and even in front of their houses before they got enough garbage bins.</li> <li>– There are fourteen garbage bins are provided and they are kept the corner of each road and now the village is almost clean except beside the creek.</li> </ul> <p><u>Photos</u></p>	
			 <p>Rubbish bin at the corner of Main Road B and Road No. 1</p>	 <p>Rubbish bin at the corner of Main Road B and Road No. 2</p>
			 <p>Rubbish bin at the corner of Main Road B and Road No. 3</p>	 <p>Rubbish bin at the corner of Main Road B and Road No. 4</p>
			 <p>Rubbish bin at Main Road - C</p>	 <p>Rubbish bin at the corner of Creek Road and 5<sup>th</sup> Street</p>



Rubbish at the creek near 1<sup>st</sup> street



Rubbish at the creek near 2<sup>nd</sup> street



Rubbish at the creek near Main Road C



Rubbish at the creek near 6<sup>th</sup> Street

(5) Fly proof toilet

Improved   
Same \*  
Worse   
\*as last week

- All of the fly proof toilets are used by people.
- No serious problem for toilet for the time being.

Condition	No. of HHs	
	This week condition	Previous week condition
Level 1	86	86
Level 2	4	4
Level 3	0	0
Level 4	0	0
No Toilet	0	0

**<Evaluation Criteria>**

***Level 1***

- Fly proof toilet is not needed to be repaired.
- No/rarely toilet unavailable

***Level 2***

- Fly proof toilet is needed to be repaired.
- Rarely toilet unavailable

***Level 3***

- Fly proof toilet is needed to be repaired.
- Often toilet unavailable
- As the result of filling the soil and also due to the heavy rain, some toilets are inconvenience to use.

***Level 4***

- Fly proof toilet is urgently needed to be repaired.
- Often toilet unavailable

**Photos**






(6)  
Electricity

Improved   
Same \*  
Worse   
*\*as last week*

- Electricity comes regularly.
- Electric poles and transformer are being supported with a good foundation.

Photos



No	Item	Condition	Description and Photos
2	(1)House Construction	No. of houses not completed (4)	<p>-House No.9, there are three houses that planned to build in plot number 9 and 10 as the plots are owned by father and son. The two houses finished const-ruktion and left one.</p> <p>-House No.64, the house construction seems to be stopped.</p> <p>-House No. 78, the house need to be carried on construction, however PAPs are living now.</p> <p>-House No. 66, the house construction seems to be stopped.</p> <p><u>Photos</u></p>



House No. 9



House No. 64



House No. 78



House No. 66

**3** Other Issues

(1). Drainage condition for rain water in their compounds

Description

Condition	No. of HHs	
	This week condition	Previous week condition
Level 1	63	63
Level 2	5	5
Level 3	0	0
Level 4	0	0

**<Evaluation Criteria>**

**Level 1**

-No mud and no standing water with their own drainage system in their compound

**Level 2**

-No mud and no standing water in their compound

**Level 3**

- Some or little mud and standing water in their compound

**Level 4**

-A lot of mud and standing water in their compound

Photos





House No. 31



House No. 19



House No. 47



House No. 64



House No. 74

(2) Plantation

- In front of their compounds, the people planted shady trees, fruit trees, vegetables and floral plants.

Description

-In front of their compounds, the people planted shady trees, fruit trees, vegetables and floral plants.

Type	No. of HHs	Remarks
Shady tree	15	Albizia, Indian almond, neem tree, etc. HH No. 20, 40, 43, 48, 51, 57, 59, 61, 62, 67, 69, 72, 73, 77, 85
Fruit tree	37	Banana, Mango, sugarcane, coconut, citrus, jack fruit etc. HH No. 3, 15, 17, 20,21, 23, 28, 30, 31, 32, 34, 37, 40, 41, 48, 51, 52, 55, 57, 58, 59, 61, 62, 63, 67, 68, 70, 71, 72, 73, 77, 78, 82, 85, 86, 88
Vegetable	20	Chili, tomato, bitter gourd, Roselle, gourd, basils, eggplant etc. HH No. 12, 17, 21, 41, 49, 58, 59, 61, 62, 63, 67, 68, 70, 71, 72, 73, 77, 82, 85, 86
Floral plant	31	Jasmine, poinsettia, orchid, kiss me quick, etc. HH No. 3, 5, 6, 8, 10, 12, 13, 14, 17, 20, 21, 22, 23, 29, 30, 31, 32, 46, 48, 58, 59, 61, 62, 65, 67, 68, 69, 72, 77, 78, 86

Photos



(3) Livestock

Description

-The people are raising chicken, geese, ducks and pigs.

Type	No. of HHs	Remarks
Chicken	6	HH No. 13, 14, 21, 59, 67, 78
Pig	3	HH No. 2, 21, 56
Goose	2	HH No. 40, 67

Photos



House No. 67



House No. 2