

Weekly Field Report

No. 36





Surveyor: Zaw La

Date Visited: 6.7.2015

Time Visited: 15:30to 16:30

Weather Condition: Sunny

The last time of heavy raining: - Yesterday

No	Item	Condition	Description and Photos
1	Condition of -		
	(1). Well	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	Description & Photos: -See ANNEX.1 - One of two wells is not very clean water, but another well and all hand pumps except near transformer are well functioned and water is clean and enough to use in the raining season. In the moment, no problem for clean water so far.
	(2). <u>Drainage</u>	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<u>Description</u> -Water level in the drainage canal reduced than last week as there was a little rained yesterday. But the stream along with the drainage canal needs to be repaired in next summer. <u>Photos</u> <div style="display: flex; flex-wrap: wrap;"> <div style="width: 50%; text-align: center;">  <p>Near well No.1</p> </div> <div style="width: 50%; text-align: center;">  <p>Near HH No.48</p> </div> <div style="width: 50%; text-align: center;">  <p>Near HH No.1</p> </div> <div style="width: 50%; text-align: center;">  <p>Near garbage pit</p> </div> </div> <p style="text-align: center;">2</p>



(3). Road

Improved
 Same *
 Worse
 *as last week

Description
 -The roads are a bit wet and there are some muddy in the roads but no problem for walking.

Photos



(4).
 Garbage
 Condition









Improved
 Same *
 Worse



Description
 -Garbage pit is used by people.
 -Garbage pit is over full and it needs to be cleaned up.
 -There are some smells from garbage pit.
 -People throw garbage at the backside of Third Row.





<u>No</u>	<u>Item</u>	<u>Condition</u>	<u>Description</u>																				
1	(5). Fly proof toilet	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> *as last week	<p>-All of fly proof toilets are used by people.</p> <table border="1" data-bbox="597 577 990 892"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>6</td> <td>6</td> </tr> <tr> <td>Level 2</td> <td>18</td> <td>18</td> </tr> <tr> <td>Level 3</td> <td>29</td> <td>29</td> </tr> <tr> <td>Level 4</td> <td>13</td> <td>13</td> </tr> <tr> <td>No Toilet</td> <td>2</td> <td>2</td> </tr> </tbody> </table> <p><Evaluation Criteria></p> <p>Level 1</p> <ul style="list-style-type: none"> -No need to repair fly proof toilet -No/rarely toilet unavailable <p>Level 2</p> <ul style="list-style-type: none"> -Need to repair fly proof toilet -Rarely toilet unavailable <p>Level 3</p> <ul style="list-style-type: none"> -Need to repair fly proof toilet -Often toilet unavailable -As the result of filling the soil and also raining, some toilets are inconvenience to use. <p>Level 4</p> <ul style="list-style-type: none"> -Need to repair urgently fly proof toilet -Often toilet unavailable -After filling the soil, some toilets need to be lifted up. <div style="display: flex; justify-content: space-around; margin-top: 20px;"> <div data-bbox="609 1486 982 1774" style="text-align: center;"> <p>Level 1</p> <p>HH No. 6</p> </div> <div data-bbox="1019 1486 1393 1774" style="text-align: center;"> <p>Level 2</p> <p>HH No. 12</p> </div> </div>	Condition	No. of HHs		This week condition	Previous week condition	Level 1	6	6	Level 2	18	18	Level 3	29	29	Level 4	13	13	No Toilet	2	2
Condition	No. of HHs																						
	This week condition	Previous week condition																					
Level 1	6	6																					
Level 2	18	18																					
Level 3	29	29																					
Level 4	13	13																					
No Toilet	2	2																					

			<div style="display: flex; justify-content: space-around;"> <div style="text-align: center;"> <p>Level 3</p>  <p>HH No. 31</p> </div> <div style="text-align: center;"> <p>Level 4</p>  <p>HH No. 18</p> </div> </div>
(6). Electricity	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<u>Description</u> -Electricity comes regularly. -Electric poles and transformer are supported in good foundation. -But, there is a hole at an electric pole which was hit by a truck car. The electric pole needs to be renovated. <u>Photos</u>	<div style="display: grid; grid-template-columns: 1fr 1fr; gap: 10px;"> <div style="text-align: center;"> <p>In front of HH No. 24</p>  </div> <div style="text-align: center;">  </div> <div style="text-align: center;"> <p>In front of HH No. 24</p>  </div> <div style="text-align: center;">  </div> </div>
No	Item	Condition	Description and Photos
2	House Construct- ion	No. of houses not completed (2)	<u>Description</u> -Renovating HH No.1 is finished. -HH No.5, the construction for kitchen, toilet and water tank seems to be started again.
			<div style="display: flex; justify-content: space-around;"> <div style="text-align: center;"> <p>HH No. 1</p>  </div> <div style="text-align: center;"> <p>HH No. 5</p>  </div> </div>

3	Living Status of PAPs (Sold house, renting, etc.)	<p><u>Description</u></p> <p>(1) House ownership (1)-1 No. of house that are owned by PAPs (50) (1)-2 No. of house that were sold (18)</p> <p>(2) Living condition (2)-1 No. of houses where PAPs live (41) (2)-2 No. of houses where not original PAPs lives (22) (2)-3 No. of houses where nobody lives (5)</p> <p>Location Map: See ANNEX.2</p>																	
4	Other issue (1). Drainage condition for rain water in their compounds	<p><u>Description</u></p> <p>-Rainy season has been started. -Most of the compounds are wet.</p> <table border="1" data-bbox="467 695 1045 953"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>14</td> <td>14</td> </tr> <tr> <td>Level 2</td> <td>30</td> <td>30</td> </tr> <tr> <td>Level 3</td> <td>20</td> <td>20</td> </tr> <tr> <td>Level 4</td> <td>4</td> <td>4</td> </tr> </tbody> </table> <p><Evaluation Criteria></p> <p>Level 1 -No mud and no standing water with their own drainage system in their compound</p> <p>Level 2 -No mud and no standing water in their compound</p> <p>Level 3 - Some or little mud and standing water in their compound</p> <p>Level 4 -A lot of mud and standing water in their compound</p> <p><u>Photos</u></p> <div style="display: flex; justify-content: space-around;"> <div data-bbox="513 1451 889 1734">  <p>HH No. 47</p> </div> <div data-bbox="961 1451 1338 1734">  <p>HH No. 45</p> </div> </div>	Condition	No. of HHs		This week condition	Previous week condition	Level 1	14	14	Level 2	30	30	Level 3	20	20	Level 4	4	4
Condition	No. of HHs																		
	This week condition	Previous week condition																	
Level 1	14	14																	
Level 2	30	30																	
Level 3	20	20																	
Level 4	4	4																	



4	(2) Plantation	<p>Description -In front of their compounds, they planted shady trees, fruit trees, vegetables and floral plants.</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 20%;">Type</th> <th style="width: 20%;">No. of HHs</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>Shady tree</td> <td style="text-align: center;">12</td> <td>Albizzia, Indian almond, etc. HH No. 2, 3, 14, 19, 20, 21, 25, 27, 29, 32, 41 and 65</td> </tr> <tr> <td>Fruit tree</td> <td style="text-align: center;">24</td> <td>Banana, Mango, sugarcane, coconut, citrus, etc. HH No. 2, 3, 4, 7, 8, 9, 11, 17, 21,24, 25, 27, 33, 37, 38, 39, 41, 43, 45, 46, 47, 48, 54 and 65</td> </tr> <tr> <td>Vegetable</td> <td style="text-align: center;">10</td> <td>Spices, peas, roselle, etc. HH No. 22, 23, 25, 27, 38, 39, 40, 42,45 and 63</td> </tr> <tr> <td>Floral plant</td> <td style="text-align: center;">20</td> <td>Many species. HH No. 2, 9, 14, 15, 17,21, 23, 27, 32, 33, 38, 39, 40, 41, 42, 43, 47, 48, 58 and 65</td> </tr> </tbody> </table>	Type	No. of HHs	Remarks	Shady tree	12	Albizzia, Indian almond, etc. HH No. 2, 3, 14, 19, 20, 21, 25, 27, 29, 32, 41 and 65	Fruit tree	24	Banana, Mango, sugarcane, coconut, citrus, etc. HH No. 2, 3, 4, 7, 8, 9, 11, 17, 21,24, 25, 27, 33, 37, 38, 39, 41, 43, 45, 46, 47, 48, 54 and 65	Vegetable	10	Spices, peas, roselle, etc. HH No. 22, 23, 25, 27, 38, 39, 40, 42,45 and 63	Floral plant	20	Many species. HH No. 2, 9, 14, 15, 17,21, 23, 27, 32, 33, 38, 39, 40, 41, 42, 43, 47, 48, 58 and 65
		Type	No. of HHs	Remarks													
		Shady tree	12	Albizzia, Indian almond, etc. HH No. 2, 3, 14, 19, 20, 21, 25, 27, 29, 32, 41 and 65													
		Fruit tree	24	Banana, Mango, sugarcane, coconut, citrus, etc. HH No. 2, 3, 4, 7, 8, 9, 11, 17, 21,24, 25, 27, 33, 37, 38, 39, 41, 43, 45, 46, 47, 48, 54 and 65													
		Vegetable	10	Spices, peas, roselle, etc. HH No. 22, 23, 25, 27, 38, 39, 40, 42,45 and 63													
Floral plant	20	Many species. HH No. 2, 9, 14, 15, 17,21, 23, 27, 32, 33, 38, 39, 40, 41, 42, 43, 47, 48, 58 and 65															

4	(3) Livestock	<p>Description -They are raising chicken, ducks, goats, pigs and cows.</p>
----------	---------------	---

-Even though they have cows, they do not keep their cows in relocation site instead they keep in their farms or other places.

Type	No. of HHs	Remarks
Cow	5	HH No. 3, 18, 42, 47 and 54
Pig	-	-
Goat	1	HH.47
Chicken and ducks	15	HH No. 4, 8, 12, 14, 28, 30, 32, 41, 47, 50, 51, 52, 55, 56 and 62

Photos



ANNEX.1

As of 6.7.2015

Water is clean and has no sand, no clay and no smell. People use this well for cooking, washing and drinking. A pulley wheel, bucket and a rope have set already but the rope is still small and it needs to be changed with a new big one for convenience using the well.



This hand pump is functioned very well. Water is clean and everyone nearby using this hand pump.

This hand pump is also functioned very well. Water is clean and everyone nearby using this hand pump.

Hand pump isn't functioned.


Water is not very clean with the rain and the well has to be repaired again after the raining season. A pulley wheel, bucket and a rope have set already but the rope is still small and it needs to be changed with a new big one for convenience using the well.



This hand pump is being also functioned very well. Water is clean and everyone living nearby are using this hand pump. Now the raining season has started and the underground water level is raising up and therefore the amount of having clean water is pretty enough to use.



This hand pump is also being functioned very well. Water is clean and everyone living nearby are using this hand pump. Now the raining season has started and the underground water level is raising up and therefore the amount of having clean water is pretty enough to use. Moreover there is a water filter tank has been setting up beside the hand pump and therefore drinking water is quite good to use.



- Closed Well
- New Well (Hand pump)
- Open Well
- Hand Pump
- Private Well

