


Surveyor: Zaw La



Date Visited: 28.7.2015


Time Visited: 10:00to 11:30

Weather Condition: raining

The last time of heavy raining: - the whole day

No	Item	Condition	Description and Photos
1	Condition of -		
	(1). Well	Improved <input type="checkbox"/> Same <input type="checkbox"/> Worse <input checked="" type="checkbox"/> * <i>*as last week</i>	Description & Photos: -See ANNEX.1 - Both of the wells are dirty with outside water that entered through the wall crack. Therefore water cannot be used and these two wells need to be rehabilitated again in summer. All hand pumps except near transformer are functioned well, water is clean and the amount is enough. People using the two wells have to use the hand pumps instead of using wells. No problem for clean water at the moment.
	(2). <u>Drainage</u>	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<u>Description</u> -Water level in the drainage canals higher than last week because there was a heavy rain last night till now. The stream along with the drainage canal needs to be rehabilitated in next summer. <u>Photos</u> <div style="display: flex; flex-wrap: wrap;"> <div style="width: 50%; text-align: center;"> <p>Near Well No. 1</p>  </div> <div style="width: 50%; text-align: center;"> <p>Near HH No. 48</p>  </div> <div style="width: 50%; text-align: center;"> <p>Near HH No. 1</p>  </div> <div style="width: 50%; text-align: center;"> <p>Near garbage pit</p>  </div> </div>

			<p>In front of HH No. 1</p> 
(3). Road	<p>Improved <input type="checkbox"/></p> <p>Same <input checked="" type="checkbox"/>*</p> <p>Worse <input type="checkbox"/></p> <p><i>*as last week</i></p>		<p><u>Description</u></p> <p>- The roads are being wet a bit and muddy in some areas but no problem for walking.</p> <p><u>Photos</u></p> <div style="display: flex; flex-wrap: wrap;"> <div style="width: 50%;"> <p>Front main road</p>  </div> <div style="width: 50%;"> <p>The right road of relocation site</p>  </div> <div style="width: 50%;"> <p>Middle road</p>  </div> <div style="width: 50%;"> <p>The left road of relocation site</p>  </div> </div>
(4). Garbage Condition	<p>Improved <input type="checkbox"/></p> <p>Same <input checked="" type="checkbox"/>*</p> <p>Worse <input type="checkbox"/></p>		<p><u>Description</u></p> <ul style="list-style-type: none"> -Garbage pit is used by people. -Garbage pit is over full and it needs to be cleaned up. -There are some smells from garbage pit. -People throw garbage at the backside of Third Row.



No
1

Item
(5). Fly
proof
toilet

Condition
Improved

Same *
Worse
*as last
week

Description
-All of fly proof toilets are used by people.

Condition	No. of HHs	
	This week condition	Previous week condition
Level 1	6	6
Level 2	18	18
Level 3	29	29
Level 4	13	13
No Toilet	2	2

<Evaluation Criteria>

Level 1

- No need to repair fly proof toilet
- No/rarely toilet unavailable

Level 2


- Need to repair fly proof toilet
- Rarely toilet unavailable

Level 3

- Need to repair fly proof toilet
- Often toilet unavailable
- As the result of filling the soil and also raining, some toilets are inconvenience to use.

Level 4

- Need to repair urgently fly proof toilet
- Often toilet unavailable
- After filling the soil, some toilets need to be lifted up.




(6).
Electricity


Improved
 Same *
 Worse
 *as last week

Description

- Electricity comes regularly.
- Electric poles and transformer are supported in good foundation.
- But, there is a hole at an electric pole which was hit by a truck car. The electric pole needs to be renovated.

Photos



No	Item	Condition	Description and Photos																	
2	House Construction	No. of houses not completed (2)	<p><u>Description</u> -HH No.5, the construction for kitchen, toilet and water tank seems to be started again.</p> 																	
3	Living Status of PAPs (Sold house, renting, etc.)	<p><u>Description</u></p> <p>(1) House ownership (1)-1 No. of house that are owned by PAPs (50) (1)-2 No. of house that were sold (18)</p> <p>(2) Living condition (2)-1 No. of houses where PAPs live (41) (2)-2 No. of houses where not original PAPs lives (22) (2)-3 No. of houses where nobody lives (5)</p> <p>Location Map: See ANNEX.2</p>																		
4	Other issue		<p>(1). Drainage condition for rain water in their compounds</p> <p><u>Description</u> -Rainy season has been started. -Most of the compounds are being wet.</p> <table border="1" data-bbox="367 1075 948 1333"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>14</td> <td>14</td> </tr> <tr> <td>Level 2</td> <td>30</td> <td>30</td> </tr> <tr> <td>Level 3</td> <td>20</td> <td>20</td> </tr> <tr> <td>Level 4</td> <td>4</td> <td>4</td> </tr> </tbody> </table> <p><Evaluation Criteria></p> <p>Level 1 -No mud and no standing water with their own drainage system in their compound</p> <p>Level 2 -No mud and no standing water in their compound</p> <p>Level 3 - Some or little mud and standing water in their compound</p> <p>Level 4 -A lot of mud and standing water in their compound</p>	Condition	No. of HHs		This week condition	Previous week condition	Level 1	14	14	Level 2	30	30	Level 3	20	20	Level 4	4	4
Condition	No. of HHs																			
	This week condition	Previous week condition																		
Level 1	14	14																		
Level 2	30	30																		
Level 3	20	20																		
Level 4	4	4																		

Photos



4 (2) Plantation

Description

-In front of their compounds, they planted shady trees, fruit trees, vegetables and floral plants.

Type	No. of HHS	Remarks
Shady tree	12	Albizia, Indian almond, etc. HH No. 2, 3, 14, 19, 20, 21, 25, 27, 29, 32, 41 and 65
Fruit tree	24	Banana, Mango, sugarcane, coconut, citrus, etc. HH No. 2, 3, 4, 7, 8, 9, 11, 17, 21,24, 25, 27, 33, 37, 38, 39, 41, 43, 45, 46, 47, 48, 54 and 65
Vegetable	10	Spices, peas, roselle, etc. HH No. 22, 23, 25, 27, 38, 39, 40, 42,45 and 63
Floral plant	20	Many species. HH No. 2, 9, 14, 15, 17,21, 23, 27, 32, 33, 38, 39, 40, 41, 42, 43, 47, 48, 58 and 65





4 (3) Livestock

Description

-They are raising chicken, ducks, goats, pigs and cows.
 -Even though they have cows, they do not keep their cows in relocation site instead they keep in their farms or other places.

Type	No. of HHs	Remarks
Cow	5	HH No. 3, 18, 42, 47 and 54
Pig	-	-
Goat	1	HH.47
Chicken and ducks	15	HH No. 4, 8, 12, 14, 28, 30, 32, 41, 47, 50, 51, 52, 55, 56 and 62


Photos



ANNEX.1

As of 28.7.2015

Water is clean and people nearby are using it for drinking and living use. A pulley wheel, bucket and a rope have been set up but the rope seems to be thin and it is better to be changed with thick one for the better use.



This well cannot be used as water is dirty. A pulley wheel, bucket and a rope have been set up but the rope seems to be thin and it is better to be changed with a thick one for the better use.



This hand pump is also functioned very well. Water is clean and everyone nearby is using this hand pump. Now the raining season has started and the groundwater level is raising up and therefore the amount of water is pretty enough to use.



This hand pump is functioned very well. Water is clean and everyone nearby is using this hand pump.

This hand pump is functioned very well. Water is clean and everyone nearby using this hand pump for drinking water and living use.

Hand pump isn't functioned.

This hand pump is functioned very well. Water is clean and everyone living nearby is using this hand pump. Moreover water filter tank for remove the smell of iron has been set up beside the hand pump. There is no smell of iron and people enjoy water for drinking and living use.



- Closed Well
- New Well (Hand pump)
- Open Well
- Hand Pump
- Private Well



-  Main Road
-  Sub-road
-  Proposed Road
-  Existing Road
-  Drainage
-  Creek
-  HHs that are owned by PAPs (50)
-  HHs that were sold (18)
-  HHs where original PAPs are living (41)
-  HHs that are rented by other people (22)
-  HHs where nobody is living (5)
-  HHs that were built by constructor (12)