

Weekly Field Report

No. 3


Surveyor: Sithu Nyein


Date Visited: 02.9.2014







Time Visited: 14:00 to 16:00







Weather Condition: Partly Cloudy


The last time of heavy raining: 5 days ago





No	Item	Condition	Description and Photos
1	<b>Condition of -</b>		
	(1). Well	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	Description & Photos: -See ANNEX.1 -Hand Pumps of Well No.6 and No.9 are needed to repair.
	(2). Drainage	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> Worse <input type="checkbox"/> <i>*as last week</i>	<u>Description</u> Water level in the drainage canal is near to the bottom.  <u>Photos</u> 





No	Item	Condition	Description and Photos
1	(3). Road	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<p><u>Description</u></p> <p>-There are some puddles and partly muddy areas but the roads are almost dry and no problem for traffic as a whole.</p> <p><u>Photos</u></p> 





No	Item	Condition	Description and Photos
1	(4). Garbage Condition	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<p><u>Description</u></p> <ul style="list-style-type: none"> <li>-Water level near garbage pit becomes lower.</li> <li>-Garbage pit is used by some people.</li> <li>-Smells are emerging from garbage pit.</li> <li>-Especially people who live in third row throw away the garbage in the backside of their compounds over the fence.</li> <li>-Some people put the garbage near electrical transformer.</li> <li>-Garbage is thrown away in the drainage canal.</li> </ul> <div style="display: flex; flex-wrap: wrap;"> <div style="width: 50%; text-align: center;">  <p>Garbage Pit</p> </div> <div style="width: 50%; text-align: center;">  <p>Garbage Pit</p> </div> <div style="width: 50%; text-align: center;">  <p>Garbage Pit</p> </div> <div style="width: 50%; text-align: center;">  <p>Garbage at the backside of HH No.49</p> </div> <div style="width: 50%; text-align: center;">  <p>Near transformer</p> </div> <div style="width: 50%; text-align: center;">  <p>Drainage canal near HH No.48</p> </div> </div>

No	Item	Condition	Description and Photos																				
1	(5). Fly proof toilet	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> Worse <input type="checkbox"/> <i>*as last week</i>	<p><u>Description</u> -All of fly proof toilets are being used by people.</p> <table border="1"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>42</td> <td>42</td> </tr> <tr> <td>Level 2</td> <td>21</td> <td>21</td> </tr> <tr> <td>Level 3</td> <td>0</td> <td>0</td> </tr> <tr> <td>Level 4</td> <td>0</td> <td>0</td> </tr> <tr> <td>No Toilet</td> <td>5</td> <td>5</td> </tr> </tbody> </table> <p><b>&lt;Evaluation Criteria&gt;</b>  <b>Level 1</b>            -No need to repair fly proof toilet            -No/rarely toilet unavailable  <b>Level 2</b>            -Need to repair fly proof toilet            -Rarely toilet unavailable  <b>Level 3</b>            -Need to repair fly proof toilet            -Often toilet unavailable  <b>Level 4</b>            -Need to repair urgently fly proof toilet            -Often toilet unavailable</p> <p><u>Photos</u></p>   	Condition	No. of HHs		This week condition	Previous week condition	Level 1	42	42	Level 2	21	21	Level 3	0	0	Level 4	0	0	No Toilet	5	5
Condition	No. of HHs																						
	This week condition	Previous week condition																					
Level 1	42	42																					
Level 2	21	21																					
Level 3	0	0																					
Level 4	0	0																					
No Toilet	5	5																					
(6).	Electricity	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> Worse <input type="checkbox"/> <i>*as last week</i>	<p><u>Description</u> -Electricity is coming regularly. -Electric poles and transformer are supported in good foundation.</p> <p><u>Photos</u></p>   																				

No	Item	Condition	Description and Photos
2	House Construction	No. of houses not completed (2)	<p><u>Description</u></p> <ul style="list-style-type: none"> <li>-HH No.1 doesn't have ladder and nobody is living.</li> <li>-In HH No.5, the construction for kitchen, toilet and water tank seems stopped. Nobody lives.</li> <li>-In HH No.5, sun shade of this house is collapsed due to wind. Wind is not so strong but the quality of the sun shade is not so good enough.</li> </ul> <p><u>Photos</u></p> 
3	Living Status of PAPs (Sold house, renting, etc.)		<p><u>Description</u></p> <p>(1) House ownership</p> <ul style="list-style-type: none"> <li>(1)-1 No. of house that are owned by PAPs (49)</li> <li>(1)-2 No. of house that were sold (19)</li> </ul> <p>(2) Living condition</p> <ul style="list-style-type: none"> <li>(2)-1 No. of houses where PAPs live (37)</li> <li>(2)-2 No. of houses where not original PAPs lives (25)</li> <li>(2)-3 No. of houses where nobody lives (6)</li> </ul> <p><b>Yellow</b> = changes from last week</p> <p>-HH No.57 is rented by people, nobody is living before.</p>
			Location Map: See ANNEX.2

No	Item	Description and Photos																
4	Other issues																	
	(1). Drainage condition for rain water in their compounds	<p><u>Description</u></p> <p>-In this week, there is no heavy rain. -But there are some puddles and muddy areas in most of the compounds.</p> <table border="1"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>6</td> <td>6</td> </tr> <tr> <td>Level 2</td> <td>24</td> <td>28</td> </tr> <tr> <td>Level 3</td> <td>23</td> <td>23</td> </tr> <tr> <td>Level 4</td> <td>15</td> <td>11</td> </tr> </tbody> </table> <p><b>&lt;Evaluation Criteria&gt;</b></p> <p><b>Level 1</b> -No mud and no standing water with their own drainage system in their compound</p> <p><b>Level 2</b> -No mud and no standing water in their compound</p> <p><b>Level 3</b> - Some or little mud and standing water in their compound</p> <p><b>Level 4</b> -A lot of mud and standing water in their compound</p> <div style="display: flex; flex-wrap: wrap; justify-content: space-around;"> <div style="text-align: center;">  <p>HH No. 47</p> <p>Level 1</p> </div> <div style="text-align: center;">  <p>HH No. 14</p> <p>Level 2</p> </div> <div style="text-align: center;">  <p>HH No. 52</p> <p>Level 3</p> </div> <div style="text-align: center;">  <p>HH No. 11</p> <p>Level 4</p> </div> </div>	Condition	No. of HHs		This week condition	Previous week condition	Level 1	6	6	Level 2	24	28	Level 3	23	23	Level 4	15
Condition	No. of HHs																	
	This week condition	Previous week condition																
Level 1	6	6																
Level 2	24	28																
Level 3	23	23																
Level 4	15	11																

No	Item	Description and Photos															
4	(2) Plantation	<p><u>Description</u> -In front of their compounds, they planted shady plants, fruit trees, vegetables and floral plants</p> <table border="1"> <thead> <tr> <th>Type</th> <th>No. of HHs</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>Shady tree</td> <td>10</td> <td>Albizia, Indian almond, etc. HH No.2, 3, 14, 20, 21, 25, 27, 32, 41, and 65</td> </tr> <tr> <td>Fruit tree</td> <td>21</td> <td>Banana, Mango, sugarcane, coconut, citrus, etc. HH No. 2, 3, 4, 7, 8, 9, 11, 17, 21, 25, 33, 37, 38, 39, 41, 43, 45, 46, 47, 48 and 65</td> </tr> <tr> <td>Vegetable</td> <td>10</td> <td>Spices, peas, roselle, etc. HH No. 22, 23, 25, 27, 38, 39, 40, 42, 45 and 63</td> </tr> <tr> <td>Floral plant</td> <td>18</td> <td>Many species HH No. 2, 9, 14, 15, 17, 23, 32, 33, 38, 39, 40, 41, 42, 43, 47, 48, 58 and 65</td> </tr> </tbody> </table>	Type	No. of HHs	Remarks	Shady tree	10	Albizia, Indian almond, etc. HH No.2, 3, 14, 20, 21, 25, 27, 32, 41, and 65	Fruit tree	21	Banana, Mango, sugarcane, coconut, citrus, etc. HH No. 2, 3, 4, 7, 8, 9, 11, 17, 21, 25, 33, 37, 38, 39, 41, 43, 45, 46, 47, 48 and 65	Vegetable	10	Spices, peas, roselle, etc. HH No. 22, 23, 25, 27, 38, 39, 40, 42, 45 and 63	Floral plant	18	Many species HH No. 2, 9, 14, 15, 17, 23, 32, 33, 38, 39, 40, 41, 42, 43, 47, 48, 58 and 65
		Type	No. of HHs	Remarks													
		Shady tree	10	Albizia, Indian almond, etc. HH No.2, 3, 14, 20, 21, 25, 27, 32, 41, and 65													
		Fruit tree	21	Banana, Mango, sugarcane, coconut, citrus, etc. HH No. 2, 3, 4, 7, 8, 9, 11, 17, 21, 25, 33, 37, 38, 39, 41, 43, 45, 46, 47, 48 and 65													
		Vegetable	10	Spices, peas, roselle, etc. HH No. 22, 23, 25, 27, 38, 39, 40, 42, 45 and 63													
Floral plant	18	Many species HH No. 2, 9, 14, 15, 17, 23, 32, 33, 38, 39, 40, 41, 42, 43, 47, 48, 58 and 65															
<u>Photos</u>																	
																	
																	
																	
																	

No	Item	Description and Photos															
4	(3) Livestock	<p data-bbox="400 300 544 329"><u>Description</u></p> <p data-bbox="400 333 1406 434">-They are raising chicken, ducks, goats, pigs and cows. -Even though they have cows, they do not keep their cows in relocation site instead they keep in their farms or other places.</p> <table border="1" data-bbox="400 472 1062 730"> <thead> <tr> <th>Type</th> <th>No. of HHs</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>Cow</td> <td>5</td> <td>HH No. 3, 18, 42, 47 and 54</td> </tr> <tr> <td>Pig</td> <td>1</td> <td>HH No. 2</td> </tr> <tr> <td>Goat</td> <td>1</td> <td>HH No. 50</td> </tr> <tr> <td>Chicken and ducks</td> <td>9</td> <td>HH No. 48, 12, 28, 30, 32, 41, 50 and 52</td> </tr> </tbody> </table> <p data-bbox="400 734 488 763"><u>Photos</u></p> <div data-bbox="432 775 898 1122">  </div> <div data-bbox="938 775 1402 1122">  </div> <div data-bbox="432 1167 898 1503">  </div> <div data-bbox="938 1167 1402 1503">  </div>	Type	No. of HHs	Remarks	Cow	5	HH No. 3, 18, 42, 47 and 54	Pig	1	HH No. 2	Goat	1	HH No. 50	Chicken and ducks	9	HH No. 48, 12, 28, 30, 32, 41, 50 and 52
Type	No. of HHs	Remarks															
Cow	5	HH No. 3, 18, 42, 47 and 54															
Pig	1	HH No. 2															
Goat	1	HH No. 50															
Chicken and ducks	9	HH No. 48, 12, 28, 30, 32, 41, 50 and 52															
5	<b>Remarks</b>	<p data-bbox="212 1547 1422 1615">-U Gan Barlu (HH No.3) happened a motor bike accident on Sept 2, 2014 and got minor injuries in his knees. And one of his cows died last week. This cow have an infant cow.</p> <p data-bbox="212 1653 1398 1753">-U Myint Thu (HH No.43) got injury in his thump on last week. The circle saw run by motor that is used for cutting woods made some cut in his thump. Not serious but he need to see a doctor every day.</p> <p data-bbox="212 1794 1374 1861">-U Zaw Latt and another man from Mekong Watch came to relocation site on September 2, 2014 according to U Myint Thu said. But their objective isn't known.</p>															





